FLUKE ®







i2500-18 iFlex Flexible Current Probe for Fluke 374 Clamp Meter

- Extend the measurement range of select Fluke Clamp Meters upto 2500A AC
- Now measure akward size conductors / bus bars with ease
- Improved wire access & ability to measure in tight spaces

Twist to unlock Pull to open

Fluke i1010 Add AC/DC Current Measurement Capability to Your FLUKE DMM

- AC/DC Current Clamp, 600A AC, 1000A DC, CAT III-600V safety rating
- 1mV/Amp output guarantees easy reading on your meter
- Maximum conductor dia Ø 30 mm



Fluke i410

Add AC/DC Current Measurement Capability to Your FLUKE DMM

- AC/DC Current Clamp, 400A AC/DC, CAT-III 600V safety rating
- 1mV/Amp output guarantees easy reading on your meter
- Maximum conductor dia Ø 30 mm

Fluke TL75 Hard Point Test Lead Set

- Extremely hard alloy to resist tip wear
- 1.5m long PVC leads with comfort grip
- CAT III-1000V, CAT IV-600V safety rating





Fluke TL175

Twist Guard Test Leads with Patented Extendable Tip

- New! Wear Guard test lead wear indicator to indicate replacement of leads
- CAT III-1000V, CAT IV- 600V safety rating
- Advanced strain relief function for extra long working life

Fluke ToolPak[™] TPAK - Toolpak Magnetic Meter Hanger

- Free both hands to make measurements
- Hangs you meter from metallic surface
- Kit includes universal hanger clips (two), hook & loop starps (2 lengths), adapter & strong magnets
- Ideal for 11x, 17x, 28x, 87V DMMs, 1503,1507,1577 & 1587 Insulation testers & 50 series digital thermometers





Fuse

Fuse for 115/15B/17B/179 Combo

Fuse, 11A, 1000V, FAST 406INX 1.5IN, BULK

- Fuse for 15B/17B
 Fuse, 500 MA, 1000 VOLT AC/DC, FAST, 6.35 X 32MM, BULK
 Fuse for 179 Combo
- Fuse for 179 Combo Fuse, 440A, 1000V, FAST, 406X 1.375, BULK
- Fuse for 1503/1507 Fuse, 315 MA, 1000 V AC/DC, FAST, 6.35 X 32 MM, BULK